

On Scene Photos

Courtesy of Southwest Aircraft Transport and Recovery



Figure 1: Main Wreckage



Figure 2: Main Rotor Blades



Figure 3: Cabin Area/Fuselage



Figure 4: Engine



Figure 5: Tailboom and Tail Rotor Assembly

END.

Submitted by: Samantha Link