



Photo 1 – Forward Quartering View of Accident Airplane During Postaccident Examination



Photo 2 – View of Accident Airplane from Right Wing During Postaccident Examination



Photo 3 – View of Primary Flight Display and Annunciator Panel



Photo 4 – Propeller During Postaccident Examination