

PHOTO ARRAY




Figure 1: Hub (showing thread wear)




Figure 2: Thread Close-Up




Figure 3: Copper Gasket (portion showing crush)



Figure 4: Other Side of Copper Gasket



Figure 5: Tear in Gasket



Figure 6: Fiber Gasket (tear)



Figure 7: Fiber Gasket (showing (extrusion))



Figure 8: Fiber Gasket (side)