



Photo 1 – Damaged Airplane (Photo Courtesy of FAA)



Photo 2 – Separated Landing Gear Axle at the Wheel (Photo Courtesy of FAA)