



Photo 1 – Fuselage Damage Right Side (FAA Photo)



Photo 2 – Fuselage Damage Forward Right Side (FAA Photo)




Photo 3 – X Pattern Skin Fracture (FAA Photo)




Photo 4 – Damaged 232 Bulkhead (FAA Photo)




Photo 5 – Damaged 205 and 232 Bulkheads (FAA Photo)