



Photo 1 – View of inverted airplane with damaged fuselage (courtesy of the FAA)



Photo 2 – View of oil residue on the belly of the airplane (courtesy of the FAA)




Photo 3 – View of left side of inverted of engine (courtesy of the FAA)



Photo 4 – View of right side of inverted engine with automotive oil bypass filter (courtesy of the FAA)