



Photo 1 – View of airplane on the runway with a collapsed left main landing gear



Photo 2 - View of extended left main landing gear with a bent upper side brace link



Photo 3 – Closeup view of bent left main landing gear upper side brace link