



Photo 1 – N3078G, Left View. Photo courtesy of first responders.



Photo 2 – N3078G Right View. Photo courtesy of first responders.



Photo 3 – N3078G Final Approach to Landing Area. Photo courtesy of first responder



Photo 4 – N3078G Instrument Panel. Photo courtesy of first responders.




Photo 5 – N3078G Engine Right Side. Photo courtesy of FAA.




Photo 6 – N3078G Engine Left Side. Photo courtesy of FAA.




Photo 7 – N3078G Engine Mounted in Test Stand. Photo courtesy of FAA.