



Photo 1 – View of Accident Airplane (Courtesy of Hurricane Valley Fire Department)



Photo 2 – Airplane Engine and Cowling (Courtesy of Accident Pilot)



Photo 3 – Throttle Arm Minutes After Accident (Courtesy of Accident Pilot)



Photo 4 – Mixture Control and Throttle Control Arms (from left to right) (Courtesy of Continental Aerospace Technologies)