



Photo 1 – Front Quartering View of Accident Airplane (Courtesy of Federal Aviation Administration)



Photo 2 – Carburetor Heat Position After Accident (Courtesy of Federal Aviation Administration)




Photo 3 – Fuel Sample Taken After Accident (Courtesy of Federal Aviation Administration)