



MEMORANDUM FOR RECORD

Stephen Stein
Air Safety Investigator
National Transportation Safety Board
Office of Aviation Safety – Western Pacific Region

Weather Report – Scappoose Industrial Airpark (SPB), Scappoose, Oregon
Date & Time: July 20, 2019; 1515 PDT
NTSB Accident Number: WPR19LA200

SPB is a nearby weather observation facility located 13 nm west of the accident site.

METAR/SPECI from KSPB, Scappoose, Scappoose Industrial Airpark (United States).		
SA	21/07/2019 07:53->	METAR KSPB 210753Z AUTO 33004KT 10SM CLR 21/09 A2993 RMK AO2 SLP133 T02060094 403060111=
SA	21/07/2019 06:53->	METAR KSPB 210653Z AUTO 33005KT 10SM CLR 22/09 A2993 RMK AO2 SLP133 T02220089=
SA	21/07/2019 05:53->	METAR KSPB 210553Z AUTO 32006KT 10SM CLR 23/09 A2992 RMK AO2 SLP131 T02280089 10300 20228 52004=
SA	21/07/2019 04:53->	METAR KSPB 210453Z AUTO 32006KT 10SM CLR 23/11 A2992 RMK AO2 SLP130 T02330106=
SA	21/07/2019 03:53->	METAR KSPB 210353Z AUTO 32006KT 10SM CLR 24/10 A2991 RMK AO2 SLP127 T02440100=
SA	21/07/2019 02:53->	METAR KSPB 210253Z AUTO 33007KT 10SM CLR 27/09 A2991 RMK AO2 SLP127 T02720094 56011=
SA	21/07/2019 01:53->	METAR KSPB 210153Z AUTO 35010G18KT 10SM CLR 29/09 A2991 RMK AO2 SLP128 T02890094=
SA	21/07/2019 00:53->	METAR KSPB 210053Z AUTO 36008KT 10SM CLR 29/08 A2992 RMK AO2 SLP133 T02940083=
SA	20/07/2019 23:53->	METAR KSPB 202353Z AUTO VRB06KT 10SM CLR 30/07 A2994 RMK AO2 SLP138 T03000072 10306 20211 58017=
SA	20/07/2019 22:53->	METAR KSPB 202253Z AUTO 36007KT 10SM CLR 30/08 A2996 RMK AO2 SLP144 T03000078=
SA	20/07/2019 21:53->	METAR KSPB 202153Z AUTO 01007KT 10SM CLR 29/09 A2997 RMK AO2 SLP149 T02890089=
SA	20/07/2019 20:53->	METAR KSPB 202053Z AUTO VRB05KT 10SM CLR 27/10 A2999 RMK AO2 SLP155 T02720100 58018=