



Photo 1 – Accident site. (Courtesy of first responders)



Photo 2 – Accident site, view of the forward side of the airplane. (Courtesy of first responders)



Photo 3 – Accident site, view from the airport property fencing. (Courtesy of first responders)



Photo 4 - Accident site, view of the forward lower engine and nose landing gear area. (Courtesy of first responders)



Photo 5 – Accident site, view of the left side fuselage. (Courtesy of first responders)



Photo 6 – Accident site, view of the nose landing gear area. (Courtesy of first responders)



Photo 7 – Accident site, view of the fuel control valve and handle. (Courtesy of first responders)



Photo 8 – Accident site, view of the left-wing tip area. (Courtesy of first responders)