



Photo 1 – Accident site, view of the forward left side of airplane. (Courtesy of the FAA)



Photo 2 – Accident site, runway tire marks. (Courtesy of the FAA)



Photo 3 – Accident site, view of the forward side of the airplane. (Courtesy of the FAA)



Photo 4 – Accident site, left wing. (Courtesy of the FAA)



Photo 5 – Nose landing gear steering control rod. (Courtesy of the FAA)



Photo 6 - Nose landing gear steering control rod, separation surface. (Courtesy of the FAA)



Photo 7 – Nose landing gear steering control rod, separation surface. (Courtesy of the FAA)



Photo 8 – Nose landing gear steering assembly, linkage separation. (Courtesy of the FAA)