

On Scene Photos
Courtesy of Local Law Enforcement



Figure 1: Aft side of Airplane



Figure 2: Front Right of Airplane

On Scene Photos
Courtesy of Local Law Enforcement



Figure 3: Front of Airplane



Figure 4: Engine

On Scene Photos
Courtesy of Local Law Enforcement



Figure 5: Left Side of Airplane



Figure 6: Empennage

On Scene Photos
Courtesy of Local Law Enforcement



Figure 7: Cabin Area

END.

Submitted by: Samantha Link