



Photo 1 – Accident site, forward right side of airplane.



Photo 2 – Accident site, forward right side of engine cowling.



Photo 3 – Accident site, view of the right side of engine area.



Photo 4 – Accident site, left side of engine.