

WPR19LA265 Accident Pictures



Figure 1: Fuel selector positioned to the right tank. (Courtesy of FAA)

09/23/2019 15:50:38

EPIC
AVIATION

Visa Sale

Transwestern Aviation - SPB
Scappoose, OR - 97056

Merchant # [REDACTED] Batch [REDACTED]
Terminal ID [REDACTED] Invoice [REDACTED]
Operator ID kev

Customer Name MICHELSEN/AARON
Card # [REDACTED] Swiped
Tail # N5277C Flight # [REDACTED]

AvGas 100
Tail Gallon
24 : 20

24.20 @ [REDACTED] /Gallon \$ [REDACTED]
StateTax-Avgas \$ [REDACTED]
FET-Avgas \$ [REDACTED]

Fuel Total \$ [REDACTED]
Invoice Total US\$ [REDACTED]

Approved : 68785G

Did you receive the correct grade of fuel?
AvGas 100
Y / N

Customer Copy

Figure 2: Fuel Receipt. (Courtesy of FAA)



Figure 3: Airplane wreckage as viewed from the right. (Courtesy of FAA).