

NATIONAL TRANSPORTATION SAFETY BOARD PILOT/OPERATOR AIRCRAFT ACCIDENT/INCIDENT REPORT

This form to be used for reporting civil and public aircraft accidents and incidents

BASIC INFORMATION

Accident/Incident Location

Nearest City/Place: Lincoln Park State: NJ

ZIP: 07035 Country: USA

Latitude: 40.95N Longitude: 74.31W

(Enter in decimal degrees or degrees:minutes:seconds)

Accident/Incident Date/Time

Date: 05/02/2019 Local Time: 1530

mm/dd/yyyy

Time Zone: EDT

Collision with Other Aircraft: ☐ Midair ☐ On-ground ☒ None

AIRCRAFT INFORMATION

Registration Number: N7532R

Manufacturer: Robinson

Model: R22 Beta II

Serial Number: 3554

Year of Manufacture: 2004

Amateur-Built: ☐ Yes ☒ No If Yes: ☐ Kit/Plans ☐ Original Design Make: _____

- ☐ IFR-Equipped and Certified
☐ Commercial Space Flight
☐ Unmanned Aircraft

Maximum Gross Weight: 1370 lbs

Weight at Time of Accident/Incident: 1300 lbs

Number of Seats: 2 Flight Crew Seats: 1

Cabin Crew Seats: 0 Passenger Seats: 1

Number of Engines: 1

Category of Aircraft

- ☐ Airplane
☐ Balloon
☐ Blimp/Dirigible
☐ Glider
☐ Gyroplane
☒ Helicopter
☐ Powered Lift
☐ Rocket
☐ Ultralight
☐ Unknown

Type of Airworthiness Certificate

(Check all that apply)

Standard

- ☒ Normal
☐ Aerobatic
☐ Balloon
☐ Commuter
☐ Transport
☐ Utility

Special

- ☐ Restricted
☐ Limited
☐ Provisional
☐ Special Flight
☐ Experimental
☐ Special Light-Sport
☐ Experimental Light-Sport

- ☐ Certificate of Authorization or Waiver (COA)
☐ None ☐ Unknown

Landing Gear

(Check all that apply)

☐ Retractable

- ☐ Tricycle ☐ Tailwheel
☐ Amphibian ☐ High Skid
☐ Emergency Float ☒ Skid
☐ Float ☐ Ski
☐ Hull ☐ Ski/Wheel
☐ Other Launch/Recovery System
☐ None ☐ Unknown

Engine Type (Select one)

- ☒ Reciprocating ☐ Liquid Rocket
☐ Turbo Shaft ☐ Solid Rocket
☐ Turbo Prop ☐ Hybrid Rocket
☐ Turbo Jet ☐ None
☐ Turbo Fan ☐ Unknown
☐ Electric

Fuel System Type (Reciprocating)

- ☒ Carburetor ☐ Fuel-Injected

Engine	Engine Manufacturer	Engine Model/Series	Manufacturer's Serial Number	Date of Mfg. mm/dd/yyyy	Rated Power ☒ Horsepower or ☐ lbs of Thrust	Total Time (hours)	Time Since: Inspection (hours)	Overhaul (hours)
Eng. 1	<u>Lycoming</u>	<u>O-360-J2A</u>	<u>L-40829-36E</u>	<u>03/29/2007</u>	<u>145</u>	<u>5872.8</u>	<u>54.3</u>	<u>1473.1</u>
Eng. 2								
Eng. 3								
Eng. 4								

Last Inspection Type

- ☐ 100-Hour ☐ Continuous Airworthiness
☐ AAIP ☐ Conditional Inspection
☒ Annual ☐ Unknown

Date Last Inspection: 03/21/2019
mm/dd/yyyy

Airframe Total Time: 5872.8 hrs

hours measured at (Select one)

- ☒ Last Inspection ☐ Time of Accident/Incident

Type of Maintenance Program (Select one)

- ☐ Annual
☐ Conditional (Amateur-built only)
☒ Manufacturer's Inspection Program
☐ Other Approved Inspection Program (AAIP)
☐ Continuous Airworthiness
☐ Other, specify: _____

Description of Fire Extinguishing System

- ☒ None
☐ Specify: _____

Propeller 1

- ☐ Fixed Pitch
☐ Controllable Pitch
☐ Ground Adjustable

Manufacturer: _____

Model: _____

Propeller 2

- ☐ Fixed Pitch
☐ Controllable Pitch
☐ Ground Adjustable

Manufacturer: _____

Model: _____

ELT Installed: ☐ Yes ☒ No

If Yes:

ELT Manufacturer: _____

Model or Part No.: _____

TSO No.: ☐ OC91 (121.5 MHz) ☐ OC91a (121.5 MHz)
☐ OC126 (406 MHz)

Was ELT still mounted in aircraft? ☐ Yes ☐ No

Was ELT still connected to antenna? ☐ Yes ☐ No

Did ELT Activate? ☐ Yes ☐ No

If activated:

Did ELT Aid in Locating Aircraft? ☐ Yes ☐ No

If not activated:

- Indicate Reason: ☐ Impact Damage
☐ Fire Damage
☐ Battery Expired/Damaged
☐ Unknown

Additional Equipment (Check all that apply)

- ☐ ADS-B
☐ Airframe Parachute
☐ Angle of Attack Indicator
☐ Autopilot
☐ Data Recorder
☐ Electronic Flight Bag or Handheld Device
☐ Electronic Multifunction Display
☐ Electronic Primary Flight Display
☐ Handheld GPS
☐ Heads Up Display
☐ Onboard Weather
☐ Satellite Tracking Device
☐ Stall Warning System
☐ Video Recording Device
☐ Other, Specify: _____

OWNER/OPERATOR INFORMATION**Registered Aircraft Owner**Name: Spitzer Helicopter LLCFractional Ownership Aircraft: ☐ Yes ☒ NoCity: Woodland HillsState: CAZIP: 91367Country: USA**Operator of Aircraft**☐ Same As Registered Owner☐ Same Address as Registered OwnerName: Garden State Helicopters, LLCDoing Business As: Garden State Helicopters

Air Carrier/Operator Designator (4 Character Code): _____

City: Lincoln ParkState: NJZIP: 07035Country: USA**Operating Certificates Held**

(Check all that apply)

- ☒ None
☐ Flag Carrier Operating Certificate (FAR 121)
☐ Supplemental
☐ Air Cargo
☐ Foreign Air Carriers (FAR 129)
☐ Rotorcraft External Load (FAR 133)
☐ Commuter Air Carrier (FAR 135)
☐ On-Demand Air Taxi (FAR 135)
☐ Commercial Air Tour (FAR 136)
☐ Agricultural Aircraft (FAR 137)
☐ Pilot School (FAR 141)
☐ Certificate of Authorization or Waiver (COA)
☐ Commercial Space Transportation
Experimental Permit
☐ Commercial Space Transportation License
☐ Other Operator of Large Aircraft

Regulation Flight Conducted Under

- ☒ FAR 91 ☐ FAR 129 ☐ FAR 415
☐ FAR 103 ☐ FAR 133 ☐ FAR 431
☐ FAR 121 ☐ FAR 135 ☐ FAR 435
☐ FAR 125 ☐ FAR 137 ☐ FAR 437
- ☐ FAR 91 Special Flight
☐ Non-US, Commercial
☐ Non-US, Non-commercial
- ☐ Public Aircraft (Select one)
☐ Armed Forces
☐ Federal
☐ State
☐ Local
☐ Unknown

Revenue Operation for FAR 121, 125, 129, 135

(Select one for each group)

- ☐ Scheduled or Commuter ☐ Domestic
☐ Non-Scheduled or Air Taxi ☐ International
- ☐ Passenger
☐ Cargo
☐ Mail Contract Only

Purpose of Flight for FAR 91, 103, 133, 137

(Select one)

- ☐ Aerial Application ☐ Firefighting ☐ Unknown
☐ Aerial Observation ☐ Flight Test
☐ Air Drop ☐ Glider Tow
☐ Air Race/Show ☒ Instructional
☐ Banner Tow ☐ Other Work Use
☐ Business ☐ Personal
☐ Executive/Corporate ☐ Positioning
☐ External Load ☐ Skydiving
☐ Ferry

Revenue Sightseeing Flight☐ Yes ☒ No**Air Medical Flight**☐ Yes ☒ No**AIRPORT INFORMATION (Fill in if accident/incident occurred on approach, landing, takeoff, departure, or within 3 miles of an airport)**Airport Name: Lincoln ParkAirport Identifier: N07Proximity to Airport: ☐ Off Airport/Airstrip ☒ On Airport/Airstrip ☐ N/ADistance From Airport Center: 0 smDirection From Airport: 0 degrees trueAirport Elevation: 182 ft. msl**Runway Information**Runway ID: 01/19 (L/R/C) Length: 2942 ft Width: 40 ft**Runway/Landing Surface (Check all that apply)**

- ☒ Asphalt ☐ Grass/Turf ☐ Macadam ☐ Water
☐ Concrete ☐ Gravel ☐ Metal/Wood
☐ Dirt ☐ Ice ☐ Snow ☐ Unknown

Condition of Runway/Landing Surface (Check all that apply)

- ☒ Dry ☐ Snow-Compacted ☐ Water-Calm
☐ Holes ☐ Snow-Crusted ☐ Water-Choppy
☐ Ice Covered ☐ Snow-Dry ☐ Water-Glassy
☐ Rough ☐ Snow-Wet ☐ Wet
☐ Rubber Deposits ☐ Soft
☐ Slush-Covered ☐ Vegetation ☐ Unknown

Approach/Departure Segment (Select one)

- ☒ Taxi ☐ VFR Departure ☐ On Instrument Approach ☐ Downwind ☐ Low Approach
☐ Takeoff ☐ IFR Departure Procedure/Clearance ☐ Landing ☐ Base ☐ Go Around
☐ Initial Climb ☐ Aborted Landing (after touchdown)
☐ Crosswind ☐ Unknown

IFR Approach (Check all that apply)

- ☒ None
- ☐ ADF/NDB ☐ PAR ☐ MLS ☐ Practice
☐ SDF ☐ Sidestep ☐ LDA ☐ GPS
☐ VOR/TVOR ☐ ILS ☐ ASR
☐ VOR/DME ☐ Localizer Only ☐ Visual
☐ TACAN ☐ LOC-back course ☐ Contact
☐ RNAV ☐ Circling
☐ Unknown

VFR Approach (Check all that apply)

- ☒ None
- ☐ Traffic Pattern ☐ Stop and Go
☐ Straight-In ☐ Touch and Go
☐ Valley/Terrain Following ☐ Simulated Forced Landing
☐ Go Around ☐ Forced Landing
☐ Full Stop ☐ Precautionary Landing
☐ Unknown

"FLIGHT CREWMEMBER 1" INFORMATION

"Flight Crewmember 1" Responsibilities at the Time of Accident/Incident

☐ Pilot
 ☐ Co-Pilot
 ☐ Student Pilot
 ☒ Flight Instructor
 ☐ Check Pilot
 ☐ Flight Engineer
 ☐ Other Flight Crew

"Flight Crewmember 1" was pilot flying ☒ Yes ☐ No

"Flight Crewmember 1" Identification

First Name: Joshua

City of Residence: Pequannock

Middle Initial: T

State: NJ ZIP: 07440

Last Name: Macemon

Country: USA

Age at time of Accident/Incident: 24 Date of Birth: mm/dd/yyyy

Certificate Number:

Degree of Injury

☒ None
 ☐ Fatal
☐ Minor
 ☐ Unknown
☐ Serious

Seat Occupied

☒ Left
 ☐ Front
 ☐ Unknown
☐ Right
 ☐ Rear
☐ Center
 ☐ Single

Restraint Type

Available

☐ None
☐ Lap only
☒ 3-point
☐ 4-point
☐ 5-point
☐ Unknown

Used

☐ None
☐ Lap only
☒ 3-point
☐ 4-point
☐ 5-point
☐ Unknown

Inflatable Restraints

☒ Not Installed
☐ Installed
☐ Not Deployed
☐ Deployed
☐ Unknown

Pilot Certificate(s) (Check all that apply)

☐ None
 ☒ Flight Instructor
 ☒ Commercial
 ☐ US Military
☐ Private
 ☐ Recreational
 ☐ Airline Transport
 ☐ Foreign
☐ Student
 ☐ Sport
 ☐ Flight Engineer

Principal Occupation

☒ Pilot
☐ Other
☐ Unknown

Medical Certificate

☐ None
 ☐ Class 3
☐ Class 1
 ☐ Driver's License (Sport Pilot only)
☒ Class 2
 ☐ Unknown

Medical Certificate Validity

☐ Without limitations/waivers
 ☐ Unknown
☒ With limitations/waivers
 ☐ N/A
☐ Special Issuance

Date of Last Medical

03/08/2019
 mm/dd/yyyy

Medical Certificate Limitations

Must wear corrective lenses.

Medical Certificate Special Issuance

N/A

Date of Last Flight Review or Equivalent, Including FAR 121/135 Checks:

05/18/2018
 mm/dd/yyyy

Flight Review Aircraft

Make: Robinson

Model: R22 Beta II

Airplane Rating(s)

(Check all that apply)
☒ None
☐ Single-Engine Land
☐ Single-Engine Sea
☐ Multiengine Land
☐ Multiengine Sea

Other Aircraft Rating(s)

(Check all that apply)
☐ None
☐ Airship
☐ Balloon
☐ Glider
☐ Gyroplane
☒ Helicopter
☐ Powered Lift

Instrument Rating(s)

(Check all that apply)
☐ None
☐ Airplane
☒ Helicopter
☐ Powered Lift

Instructor Rating(s)

(Check all that apply)
☐ None
 ☐ Instrument Airplane
☐ Airplane Single-Engine
 ☒ Instrument Helicopter
☐ Airplane Multi-Engine
 ☒ Helicopter
☐ Gyroplane
 ☐ Glider
☐ Powered Lift
 ☐ Sport

Type Ratings

R22 PIC Endorsement (SFAR 73) - 01/25/2013
 R22 CFI Endorsement (SFAR 73) - 05/29/2018

Student Endorsements (Include dates)

N/A

Flight Time (Enter appropriate number of hours in each box)	All Aircraft	This Make & Model	Airplane Single Engine	Airplane Multiengine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air
						Actual	Simulated			
Total Time	1,514	507	0	0	101	0	101	1,514	0	0
Pilot in Command (PIC)	1,437	444	0	0	95	0	97	1,437	0	0
Time as Instructor	881	243	0	0	35	0	0	881	0	0
This Make/Model					35	0	0			
Last 90 Days	143	78	0	0	12	0	0	143	0	0
Last 30 Days	49	27	0	0	5	0	0	49	0	0
Last 24 Hours	4	3	0	0	0	0	0	4	0	0

“Flight Crewmember 2” Responsibilities at the Time of Accident/Incident

“Flight Crewmember 2” was pilot flying ☐ Yes ☒ No

First Name: Angelo City of Residence: Oak Ridge
Middle Initial: S State: NJ ZIP: 07438
Last Name: Chupungco Country: USA
Age at time of Accident/Incident: 44 Date of Birth: *mm/dd/yyyy*
Certificate Number: N/A

Degree of Injury ☒ None ☐ Fatal ☐ Minor ☐ Unknown ☐ Serious	Seat Occupied ☐ Left ☐ Front ☐ Unknown ☒ Right ☐ Rear ☐ Center ☐ Single	Restraint Type Available ☐ None ☐ Lap only ☒ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Inflatable Restraints ☒ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown
Pilot Certificate(s) <i>(Check all that apply)</i> ☒ None ☐ Flight Instructor ☐ Commercial ☐ US Military ☐ Private ☐ Recreational ☐ Airline Transport ☐ Foreign ☐ Student ☐ Sport ☐ Flight Engineer			
Principal Occupation ☐ Pilot ☒ Other ☐ Unknown	Medical Certificate ☒ None ☐ Class 3 ☐ Class 1 ☐ Driver's License (Sport Pilot only) ☐ Class 2 ☐ Unknown	Medical Certificate Validity ☐ Without limitations/waivers ☐ Unknown ☐ With limitations/waivers ☒ N/A ☐ Special Issuance	Date of Last Medical <u>N/A</u> mm/dd/yyyy

N/A

N/A

Date of Last Flight Review or Equivalent, Including FAR 121/135 Checks: <u> N/A </u> <i>mm/dd/yyyy</i>	Flight Review Aircraft Make: <u> N/A </u> Model: <u> N/A </u>
--	--

Airplane Rating(s) <i>(Check all that apply)</i> ☒ None ☐ Single-Engine Land ☐ Single-Engine Sea ☐ Multiengine Land ☐ Multiengine Sea	Other Aircraft Rating(s) <i>(Check all that apply)</i> ☒ None ☐ Airship ☐ Balloon ☐ Glider ☐ Gyroplane ☐ Helicopter ☐ Powered Lift	Instrument Rating(s) <i>(Check all that apply)</i> ☒ None ☐ Airplane ☐ Helicopter ☐ Powered Lift	Instructor Rating(s) <i>(Check all that apply)</i> ☒ None ☐ Airplane Single-Engine ☐ Airplane Multi-Engine ☐ Gyroplane ☐ Powered Lift ☐ Instrument Airplane ☐ Instrument Helicopter ☐ Helicopter ☐ Glider ☐ Sport
--	---	---	--

Type Ratings	Student Endorsements <i>(Include dates)</i>
None	N/A

[illegible]

ADDITIONAL FLIGHT CREWMEMBERS (Exclusive of cabin crew, complete the following information)									
Crew Name and Address					Seat Occupied		Injury		
First Name: _____ City of Residence: _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____					☐ Left ☐ Front ☐ Center ☐ Rear ☐ Right ☐ Single ☐ Unknown		☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown		
Pilot Certificate(s) (Check all that apply) ☐ None ☐ Private ☐ Student ☐ Flight Instructor ☐ Recreational ☐ Sport ☐ Commercial ☐ Airline Transport ☐ Flight Engineer ☐ US Military ☐ Foreign					Restraint Type: Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown		Inflatable Restraints ☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown		
Type Rating/Endorsement for Accident/Incident Aircraft? ☐ Yes ☐ No			Total Flight Time at the Time of this Accident/Incident: _____ hrs						
Crew Name and Address					Seat Occupied		Injury		
First Name: _____ City of Residence: _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____					☐ Left ☐ Front ☐ Center ☐ Rear ☐ Right ☐ Single ☐ Unknown		☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown		
Pilot Certificate(s) (Check all that apply) ☐ None ☐ Private ☐ Student ☐ Flight Instructor ☐ Recreational ☐ Sport ☐ Commercial ☐ Airline Transport ☐ Flight Engineer ☐ US Military ☐ Foreign					Restraint Type: Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown		Inflatable Restraints ☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown		
Type Rating/Endorsement for Accident/Incident Aircraft? ☐ Yes ☐ No			Total Flight Time at the Time of this Accident/Incident: _____ hrs						
PASSENGER(S) / OTHER PERSONNEL (Include cabin crew; continue on separate sheet if necessary)									
Name and Address			Seat	Injury	Restraint Type		Inflatable Restraints	Age	
First Name: _____ City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other			☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years <i>If Under 5,</i> ☐ Child Restraint ☐ Lap-Held ☐ Unknown	
First Name: _____ City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other			☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years <i>If Under 5,</i> ☐ Child Restraint ☐ Lap-Held ☐ Unknown	
First Name: _____ City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other			☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years <i>If Under 5,</i> ☐ Child Restraint ☐ Lap-Held ☐ Unknown	
First Name: _____ City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other			☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years <i>If Under 5,</i> ☐ Child Restraint ☐ Lap-Held ☐ Unknown	

FLIGHT ITINERARY INFORMATION

Last Departure Point Airport ID: <u>N07</u> City: <u>Lincoln Park</u> State: <u>NJ</u> Country: <u>USA</u>	Time of Departure Time: <u>1500</u> Time Zone: <u>EDT</u>	Destination Airport ID: <u>N07</u> City: <u>Lincoln Park</u> State: <u>NJ</u> Country: <u>USA</u>	Type Flight Plan Filed ☒ None ☐ VFR/IFR ☐ Company VFR ☐ IFR ☐ Military VFR ☐ Unknown ☐ VFR Activated? ☐ Yes ☐ No ☐ Unknown
---	--	--	---

Type of ATC Clearance/Service (Check all that apply)				
☒ None	☐ Special VFR	☐ Special IFR	☐ VFR Flight Following	☐ Cruise
☐ VFR	☐ IFR	☐ VFR On Top	☐ Traffic Advisory	☐ Unknown / NA

Airspace where the accident/incident occurred (Check all that apply)			Altitude of In-Flight Occurrence: <u>192</u> ft msl
☐ Class A ☐ Class B ☐ Class C ☐ Class D ☐ Class E	☒ Class G ☐ Demo Area ☐ Warning Area ☐ Prohibited Area ☐ Restricted Area	☐ Military Operations Area (MOA) ☐ Airport Advisory Area ☐ Jet Training Area ☐ TRSA ☐ FAR 93	☐ Special ☐ Air Traffic Control Area ☐ Unknown

WEATHER INFORMATION AT THE ACCIDENT/INCIDENT SITE

Source of Pilot Weather Information (Check all that apply)	Weather Observation Facility
☒ National Weather Service ☐ Flight Service Station ☐ TV/Radio ☐ Automated Report ☒ Commercial Weather Service (DUATS) ☐ On-Board Weather	Facility ID: <u>KCDW</u> Observation Time: <u>1853</u> Time Zone: <u>UTC</u> Distance from Accident Site: <u>4.6</u> nm Direction from Accident Site: <u>174</u> degrees true

Basic Conditions ☒ VMC ☐ IMC ☐ Unknown	Light Condition ☐ Dawn ☐ Dusk ☐ Dark Night ☐ Unknown ☒ Day ☐ Night ☐ Bright Night
---	---

Sky/Lowest Cloud Condition ☐ Clear ☐ Thin Broken ☒ Few ☐ Thin Overcast ☐ Partial Obscuration ☐ Unknown ☐ Scattered Lowest Cloud Condition Height <u>11,000</u> ft agl	Ceiling ☒ None (Clear) ☐ Obscured ☐ Broken ☐ Indefinite ☐ Overcast ☐ Unknown Ceiling Height _____ ft agl	Temperature: <u>27</u> (C) or _____ (F) Dew Point: <u>16</u> (C) or _____ (F) Altimeter Setting: <u>30.07</u> in. Hg or _____ MB
--	--	--

Wind Direction ☒ Variable -or- Direction: _____ degrees true	Wind Speed ☐ Calm ☒ Light and Variable -or- Speed: _____ kts	Wind Gusts ☐ Not Gusting -or- Speed: _____ kts	Visibility <u>10</u> miles RVR: _____ feet RVV: _____ miles Density Altitude: <u>1630</u> ft
--	--	---	---

Intensity of Precipitation ☐ Light ☐ Moderate ☐ Heavy ☒ N/A ☐ Unknown	Type of Precipitation (Check all that apply)	Restriction to Visibility (Check all that apply)
☒ None ☐ Rain ☐ Snow ☐ Hail ☐ Rain Showers	☐ Drizzle ☐ Ice Pellets ☐ Snow Pellets ☐ Snow Grains ☐ Ice Crystals	☒ None ☐ Blowing Dust ☐ Blowing Sand ☐ Blowing Snow ☐ Blowing Spray ☐ Dust

Icing Forecast Amount ☒ None ☐ Trace ☐ Light ☐ Moderate ☐ Severe ☐ Unknown Type ☒ N/A ☐ Rime ☐ Clear ☐ Mixed ☐ Unknown	Icing Actual Amount ☒ None ☐ Trace ☐ Light ☐ Moderate ☐ Severe ☐ Unknown Type ☒ N/A ☐ Rime ☐ Clear ☐ Mixed ☐ Unknown	Turbulence Type (Check all that apply) ☒ None ☐ Clear Air ☐ Terrain-Induced ☐ Convective Turbulence Severity ☐ Light ☐ Moderate ☐ Severe ☐ Extreme
--	--	--

NOTAMs (D and FDC), AIRMETs, SIGMETs, PIREPs in effect at the time of the accident/incident:

!MIV 04/082 N07 OBST TOWER LGT (ASR 1045844) 410041.00N0741803.00W (3.9NM NE N07) 721.1FT (499.0FT AGL)
 OUT OF SERVICE 1904210051-1905212359

DAMAGE TO AIRCRAFT AND OTHER PROPERTY**Aircraft Damage**

- ☐ None ☐ Substantial
☐ Minor ☒ Destroyed
 ☐ Unknown

Aircraft Fire

- ☒ None ☐ Both Ground and In-Flight
☐ In-Flight ☐ Fire at Unknown Time
☐ On-Ground ☐ Unknown

Aircraft Explosion

- ☒ None ☐ Both Ground and In-Flight
☐ In-Flight ☐ Explosion at Unknown Time
☐ On-Ground ☐ Unknown

Description of Damage to Aircraft and Other Property *(Use additional sheet if necessary)*

Aircraft rolled. Main rotor and associated pitch/control linkages destroyed. Tail rotor assembly detached from aircraft. Skids bent and partially detached in the rear of the aircraft. Damage to frame. Windshield broken on aircraft's right side.

NARRATIVE HISTORY OF FLIGHT *(Please type or print in ink)*

Describe what occurred in chronological order, including circumstances leading to and nature of accident/incident. Describe terrain and include wreckage distribution sketch if pertinent. Attach extra sheets if needed. State departure time and location, services obtained, and intended destination. Provide as much detail as possible.

Aircraft was fueled and preflighted prior to departure. Weather observations, forecasts, and NOTAMs were also checked. A weight and balance was completed and found to be within limits. The student was briefed on information required by SFAR 73, safety information, and the plan for the flight. Flight departed Lincoln Park Airport (N07) at approximately 1500 local for the purpose of an introductory flight lesson. Nothing abnormal noted on start-up. Using my own observations of the weather, I saw winds were calm using a windsock and two flags located on the airport. Flight departed to the north using runway 01 and was operated between 700-1500 AGL. Nothing abnormal occurred and the flight went as planned. The student had done very well controlling the aircraft during the flight and we still had approximately fifteen minutes of time remaining for the lesson (it was planned on being between 30-45 minutes long) so it was decided that we would return to the airport for hovering practice. I landed the aircraft on runway 19, noting that winds were light and variable using my own observations, and proceeded to taxi to the grass area west of the runway on the southern portion of the airport. I explained each control to the student again and explained how the controls would be much more sensitive in a hover than in forward flight, again reminding him not to make any large or abrupt movements. We completed this portion of the flight at a hover height of approximately 5-10 feet from the surface and away from obstacles. After a brief time on each control, we decided to end the flight. I took back all controls of the aircraft and proceeded to begin a taxi back to our parking area. As I was about to begin forward movement to the north from a stable hover, while still at 5-10 feet, simultaneously the low RPM warning horn was heard as the aircraft began a violent yaw to the right and the nose pitched up. I now believe the perceived nose pitch-up was caused by the aircraft not being completely level in attitude when the right yaw occurred. I immediately attempted to regain control of the aircraft by rolling the throttle off to try to arrest the rate of yaw; however, as I did this I felt the tail rotor strike the ground, which caused the aircraft to spin faster. Due to the rate of the spin I was unable to determine the aircraft's attitude. At this point the only thing I could try to do was land the aircraft level. At some point, I raised the collective a fair amount, trying to estimate how above the ground we were, in order to soften the landing. I am unsure what attitude the aircraft landed in, again because the speed of rotation was too fast for me to be able to properly see outside. From the start of the accident sequence to the aircraft coming to a complete stop, I estimate to be about 3-5 seconds, during which, I estimate we did a full 360 degree rotation between 4-7 times. The aircraft came to rest on its right side. Once the aircraft fully stopped, I moved the mixture control to full lean, turned off all electronics, moved the ignition key to off, and turned off the fuel using the fuel-shutoff switch in order to try to prevent any possible post-crash fire. The aircraft was then evacuated and proper persons were notified.

RECOMMENDATION (How could this accident/incident have been prevented?)

Operator/Owner Safety Recommendation

No low-level operations during introductory lessons.

MECHANICAL MALFUNCTION/FAILURE (If more space is needed, continue on separate sheet)

Was there Mechanical Malfunction/Failure? ☐ Yes ☐ No
(If yes, list the name of the part, manufacturer, part no., serial no., and describe the failure.)

**Total Time/Cycles
On Part**

_____ Hours

_____ Cycles

**Time Since This Part
Inspected/Overhauled**

_____ Hours

FUEL & SERVICES INFORMATION**Fuel on Board at Last Takeoff**

(Convert from pounds, as necessary)

16 Gallons**Fuel Type**☐ 80/87☐ 115/145☐ Jet B☐ Other, specify _____☒ 100 Low Lead☐ Jet A☐ JP8☐ 100/130☐ Jet A-1☐ Automotive**Other Services, if Any, Prior to Departure**

None

EVACUATION OF AIRCRAFT**Was an emergency evacuation of the aircraft performed?** ☒ Yes ☐ No**Method of Exit** – Describe how the occupants exited and how many occupants evacuated each location

Each occupant exited the aircraft on their own through the left door.

OTHER AIRCRAFT – COLLISION (If air or ground collision occurred, complete this section for other aircraft)**Aircraft Registration Number**

Manufacturer: _____**Model:** _____**Damage to Other Aircraft**☐ Destroyed☐ Minor☐ Substantial☐ None**Registered Owner of Other Aircraft**

Name: _____

City: _____

State: _____ ZIP: _____

Country: _____

Pilot of Other Aircraft

Name: _____

City: _____

State: _____ ZIP: _____

Country: _____

ADDITIONAL INFORMATION (Please type or print in ink)

Use this space if additional space is needed for any answers.

I HEREBY CERTIFY THAT THE ABOVE INFORMATION IS COMPLETE AND ACCURATE TO THE BEST OF MY KNOWLEDGE

Date of this Report

05/15/2019

mm/dd/yyyy

Name of Pilot/Operator: Joshua Macemon

Signature: _____

-- or --



Check here to electronically sign this document

If a Person Other than Pilot/Operator is Filing Report

Name: _____

Title: _____

Signature: _____

-- or --



Check here to electronically sign this document

FOR NTSB USE ONLY

NTSB Accident/Incident No.

WPR19LA131

Reviewed by NTSB Regional Office

WPR

Name of Investigator

Zoë Keliher

Date Report Received

5/16/19