



Photo 1 – Photo of the right wing. Courtesy of the FAA.



Photo 2 - Photo of the right wing. Courtesy of the FAA.



Photo 3 – Photo of the parked aircraft. Courtesy of Signature Aviation.




Photo 4 – Google Earth Image of Collision Area.