



Photo 1 – View Accident Airplane from Right Wing



Photo 2 – Puncture and Leading Edge Damage to Left Wing



Photo 3 – Left Wing Lower Skin Damage