



Photo 1 – Main Wreckage at Accident Site



Photo 2 – Main Wreckage and Part of Debris Field



Photo 3 – Fuselage and Tail Remnants



Photo 4 –Main Wreckage from Tail



Photo 5 – Propeller Blades and Hub in Debris Field




Photo 6 – Elevator Trim Jackscrew Position Comparison Between Accident Airplane and Exemplar