

YEAR: DATE	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
Airframe: Piper				Woodhouse Aviation, LLC  Tach: 180.3 TTA:
Model: PA22-108				
Serial #: 22-8411				
Reg #: N4837Z				
Aired up all tires. Aired up nose strut to proper height. Removed battery box, sand blasted, primed and painted. Reinstalled battery box. Reinstalled a new battery, FAA/PMA approved Gill Part #7035-28, serial #G02983572. Copy of FAA/PMA approval and warranty added to aircraft files. Top charged battery and installed.				
Date: 02/20/2019 Inspector: [REDACTED] Brett Woodhouse, A&P [REDACTED]				

2/11/2020	TACH TIME = 180.3	CHARGED BATTERY, SERVICED TIRES. C/W A.D. 60-10-08 (FUEL SELECTOR DETENT) PER SB 141. C/W AD 68-05-01 (EX HEAT EXCHANGER). C/W AD 76-07-12 (MAGNETO SWITCH) BY OPS CHECK. PERFORMED ANNUAL INSPECTION WITH REF TO FAR 43 AppD. I CERTIFY THAT I HAVE GIVEN THIS AIRCRAFT AN ANNUAL INSPECTION AND HAVE DETERMINED IT TO BE IN AN AIRWORTHY CONDITION. [REDACTED] A&P [REDACTED] I.A.
-----------	-------------------	---

[illegible]