



Photo 1 – Accident site, initial ground impact marks. (Courtesy of the FAA)



Photo 2 – Accident site, left engine propeller ground marks. (Courtesy of the FAA)




Photo 3 – Accident site, right propeller ground marks. (Courtesy of the FAA)



Photo 4 – Accident site, initial ground impact marks. (Courtesy of the FAA)



Photo 5 – Accident site, ground marks near the edge of a coulee. (Courtesy of the FAA)



Photo 6 – Right outboard wing section and tip tank. (Courtesy of the FAA)



Photo 7 – Accident site, main wreckage. (Courtesy of the FAA)



Photo 8 – Accident site, main wreckage. (Courtesy of the FAA)



Photo 9 – Accident site, right engine and propeller. (Courtesy of the FAA)



Photo 10 – Accident site, left propeller assembly. (Courtesy of the FAA)