



Photo 1 – Photo of the airplane accident site. Courtesy of local law enforcement.




Photo 2 – View of the top side of the engine.



Photo 3 - View of the number 4 cylinder bore, piston, and a portion of the connecting rod.