



Photo 1 – View of the airplane at the accident site. Courtesy of the FAA.



Photo 2 - View of the airplane at the accident site. Courtesy of the FAA.



Photo 3 – View of the located tow rope. Courtesy of the Glider Club.



Photo 4 - View of the located tow rope. Courtesy of the Glider Club.



Photo 5 – View of the tow airplane guillotine.



Photo 6 – View of the recovered engine.