

On Scene Photos
Courtesy of the Santa Barbara County Sheriff's Department



Figure 1: Overview of Accident Site



Figure 2: Main Wreckage Came to Rest Near a Shipping Container



Figure 3: Parachute was Extended from the Airplane



Figure 4: Parachute



Figure 5: View from Parachute toward Main Wreckage



Figure 6: Wing Skin, Nose Landing Gear Assembly, and Main Wreckage.



Figure 7: Forward Left side of Main Wreckage



Figure 8: The Cabin Area



Figure 9: Aft Fuselage and Empennage



Figure 10: Left Wing



Figure 11: Empennage



Figure 12: Vertical and Horizontal Stabilizers



Figure 13: The Aft Right Side of the Airplane



Figure 14: Right Side of Airplane



Figure 15: Empennage



Figure 16: The Propeller Hub and Blades



Figure 17: The Engine



Figure 18: The Right Side Wing Spar



Figure 19: The Parachute Deployment Bag and Rocket