



Photo 1 – View accident airplane from outboard right wing (Courtesy of operator)



Photo 2 – Right horizontal stabilizer (Courtesy of Fox Aviation)



Photo 3 – Right main landing gear support tubing (Courtesy of Fox Aviation)