



Photo 1 – Main wreckage at accident site (Courtesy of Fremont County Fire Protection District)



Photo 2 – View of Accident Airplane from Left Wing (Courtesy of Fremont County Fire Protection District)



Photo 3 – View of Accident Airplane from Right Wing (Courtesy of Fremont County Fire Protection District)



Photo 4 – View of Empennage at Accident Site (Courtesy of Fremont County Fire Protection District)



Photo 5 – View of Accident Airplane from the Rear (Courtesy of Fremont County Fire Protection District)



Photo 6 – View of Accident Airplane from Engine after Airplane Recovery from Water (Courtesy of Fremont County Fire Protection District)



Photo 7 – View of Propeller after Airplane Recovery from Water (Courtesy of Fremont County Fire Protection District)