



Photo 1 –N342J, front-left view. The fenestron and vertical stabilizer are in the background. Photo courtesy of the pilot.



Photo 2 – Left view showing the main rotor hub, left skid. Photo courtesy of the pilot.



Photo 3 – Fenestron and horizontal elevators. Photo courtesy of the pilot.



Photo 4 – Left-rear view of the wreckage. Photo courtesy of the pilot.



Photo 5 – Vertical stabilizer. Photo courtesy of the pilot.