



Photo 1 – accident site looking east (photo courtesy of Centerville, Utah Police Department)



Photo 2 – photo of accident site looking west (photo courtesy of Centerville, Utah Police Department)



Photo 3 – photo of accident site looking east (photo courtesy of Centerville, Utah Police Department)



Photo 4 – photo of accident site looking southwest (photo courtesy of Centerville, Utah Police Department)