



Photo 1 – View of Main Wreckage from Left Wing (Courtesy of Federal Aviation Administration)



Photo 2 – View of Left Wing from Leading Edge (Courtesy of Federal Aviation Administration)



Photo 3 – Fuel System Header Tank with Fuel Fitting/Line to Engine Circled (Courtesy of New Owner)



Photo 4 – Fuel Header Tank Fittings (Courtesy of New Owner)