

On Scene and Recovery Photos
Courtesy of the Federal Aviation Administration and Air Transport



Figure 1: Airplane's Resting Location



Figure 2: Empennage

On Scene and Recovery Photos
Courtesy of the Federal Aviation Administration and Air Transport



Figure 3: Right Side of Airplane



Figure 4: Damage to the Spinner and Propeller Blades

On Scene and Recovery Photos
Courtesy of the Federal Aviation Administration and Air Transport



Figure 5: Left side of Airplane



Figure 6: Roof Damage (Post Airplane Recovery)

END.

Submitted by: Samantha Link