



Photo 1 – View of the airplane at the accident site. Courtesy of local law enforcement.



Photo 2 - View of the airplane at the accident site. Courtesy of local law enforcement.




Photo 3 - View of the idler gear and idler gear shaft area and accessory gears. Courtesy of the Federal Aviation Administration.