





**Photo 1 – Overview of Accident Area (Photo Courtesy of Google Earth)**



**Photo 2 – Overview of Accident Site (Photo Courtesy of Google Earth)**



**Photo 3 – Overview of Accident Site (Photo Courtesy of Google Earth)**



**Photo 4 – Aerial View of Accident Site Photo 1 – Overview of Accident Area (Photo Courtesy of FAA)**



**Photo 5 – Cable Braiding Signatures on Vertical Fin (Photo Courtesy of FAA)**



**Photo 6 – Close up View of Cable Braiding Signatures (Photo Courtesy of FAA)**



**Photo 7 – View of Long Line with the Cable Unbraided (Photo Courtesy of FAA)**



**Photo 8 – Closeup View of the Long Line (Photo Courtesy of FAA)**



**Photo 9 – Long Line Tangled in the Tail Rotor (Photo Courtesy of FAA)**



**Photo 10 – Underside of Helicopter with Attached Long Line (Photo Courtesy of FAA)**