



Photo 1 – Accident site, aft cabin and wing section. (Courtesy of Local Law Enforcement)



Photo 2 – Accident site, debris field. (Courtesy of Local Law Enforcement)



Photo 3 – Accident site, cabin area. (Courtesy of Local Law Enforcement)



Photo 4 – Accident site, wing sections. (Courtesy of Local Law Enforcement)