



Photo 1 – View of accident airplane (photo courtesy of the FAA)



Photo 2 - View of horizontal stabilizer damage (photo courtesy of the FAA)



Photo 3 - View of mechanical hydraulic pump seal damage (photo courtesy of the FAA)



Photo 4 - View of mechanical hydraulic pump seal damage (photo courtesy of the maintenance facility)




Photo 5 - View of mechanical hydraulic pump load spring damage (photo courtesy of the maintenance facility)