

WPR20LA304 Accident Site Pictures (Courtesy of Law Enforcement)



Figure 1: View of tree cut near the top.



Figure 2: View of airplane wreckage from the right side.