



Photo 1 – View of the accident airplane at the accident site. Courtesy of local law enforcement.



Photo 2 - View of the accident airplane at the accident site. Courtesy of local law enforcement.



Photo 3 – Airplane at Vacaville, California. Courtesy of a witness.



Photo 4 - Airplane at Vacaville, California. Courtesy of a witness.



Photo 5 – View of one of the engines and propeller assembly.



Photo 6 - View of one of the engines and propeller assembly.



Photo 7 -Forward portion of the fuselage.



Photo 8 – Aft portion and center portion of the fuselage and inboard portions of the wings.



Photo 9 – Empennage