



Photo 1 – Accident site, view from the runway apron.



Photo 2 – Accident site, view from near the accident site to the approach end of the runway.



Photo 3 – Accident site, right side view of the main wreckage.



Photo 4 – Accident site, lower left side view of the tail cone and tie down loop.



Photo 5 – Accident site, lower view of the tail cone and tail tie down loop.



Photo 6 – Accident site, right side view of the tail cone.



Photo 7 – Accident site, forward view of the separated empennage.



Photo 8 – Accident site, view of the left side aft fuselage.



Photo 9 – Accident site, view of the right side aft fuselage.



Photo 10 – Accident site, view of the right horizontal stabilizer tip.



Photo 11 -