



Photo 1 –N4132W Front view, showing damage to the left-wing leading edge. Photo courtesy of the pilot.



Photo 2 -N4132W, showing damage to the left-wing leading edge. Photo courtesy of the pilot.