

Additional On Scene Photos

Photos Courtesy of Josh Cawthra, NTSB



Figure 1: Overview of Accident Site



Figure 2: Left Side of Airplane

Additional On Scene Photos

Photos Courtesy of Josh Cawthra, NTSB



Figure 3: Cabin Area



Figure 4: Empennage

Additional On Scene Photos

Photos Courtesy of Josh Cawthra, NTSB



Figure 5: Right Wing Damage Consistent with Tree Impact.



Figure 6: Left Wing Leading Edge

Additional On Scene Photos

Photos Courtesy of Josh Cawthra, NTSB



Figure 7: Right Wing Leading Edge



Figure 8: Engine Controls

END. Submitted by Samantha Link