



Photo 1 – Airplane wreckage at the accident site



Photo 2 - Airplane wreckage at the accident site



Photo 3 – Damage to tree above wreckage