



Photo 1 – Forward quartering view of airplane at accident site (NTSB)



Photo 2 – Cargo items removed from aft cabin (NTSB)



Photo 3 – Accident airplane cabin interior (Courtesy of Coconino County Sheriff's Office)