



Photo 1 – View of the damage to the lower fuselage structure and left main landing gear attachment points (Courtesy of FAA)



Photo 2 – View of substantial damage to the firewall (Courtesy of FAA)



Photo 3 – View of damage to the right main landing gear attachment points (Courtesy of FAA)