



Photo 1 – Accident site, impacted tree and culvert perimeter fence. (Courtesy of the FAA)



Photo 2 – Accident site, culvert perimeter fence and culvert. (Courtesy of the FAA)



Photo 3 – Accident site, main wreckage. (Courtesy of the FAA)