



Photo 1 – view of damage to leading edge of right wing (photo courtesy of Yavapai Sheriff's Department)



Photo 2 – view of damaged left aileron (photo courtesy of Yavapai Sheriff's Department)