

On Scene Photos
Courtesy of Local Law Enforcement



Figure 1: Front of Helicopter



Figure 2: Underside of Helicopter

On Scene Photos
Courtesy of Local Law Enforcement



Figure 3: Skids and Aft Fuselage




Figure 4: Forward Fuselage

END.
Submitted by Samantha Link