



Photo 1 – N81KP view of left wing damage (photo courtesy of the FAA)



Photo 2 – N81KP view of aft fuselage damage (photo courtesy of the FAA)



Photo 3 – N18MA view of left wing damage (photo courtesy of the FAA)