



Photo 1 – N975G Front, courtesy Airport Ops



Photo 2 - N975G Right Side, courtesy Airport Ops



Photo 3 - N975G Ground Scar, courtesy FAA FSDO



Photo 4 - N975G Right Wing Damage, courtesy owner



Photo 5 - N975G Front, courtesy owner



Photo 6 - N975G Fuselage and flap, right side, courtesy owner



Photo 7 - N975G Left Landing Gear, courtesy owner



Photo 8 - N975G Left Flap, courtesy owner




Photo 9 - N975G Broken Crankshaft, courtesy FAA FSDO



Photo 10 – N975G Broken Crankshaft, courtesy FAA FSDO