




Photo 1 – Airplane at accident site (Courtesy of Airport Manager)



Photo 2 – View of cockpit at accident site (Courtesy of Airport Manager)



Photo 3 – Cylinder 2 and 4 intake valve tappets (Courtesy of Lycoming Engines)



Photo 4 – Oil suction screen (Courtesy of Lycoming Engines)