



Photo 1 – N322TR Initial View of Accident Site, courtesy of Sheriff



Photo 2 – N322TR Front, courtesy of Sheriff



Photo 3 – N322TR Ground Scars, courtesy of Sheriff



Photo 4 – N322TR Underside of Empennage and Fuselage, courtesy of Sheriff



Photo 5 – N322TR Front, courtesy of Sheriff



Photo 6 – N322TR Underside, courtesy of Sheriff